9317 MEN'S AXIS SOFT SHELL JACKET

MEN'S SIZES S-5XL

BACK VIEW

- :: A new single-layer soft shell our lightest ever
- :: Naturally breathable and water-resistant
- :: Also available in Women's sizes, style 5317





COMFORT & CONVENIENCE

- ** A new style of single-layer, lightweight soft shell that is flexible and allows for greater range of motion
- ** Naturally breathable and water-resistant without the need for a fabric treatment
- :: Wind flap provides enhanced wind protection
- :: Non-bulky fit for easy of movement and added comfort
- :: Tricot-lined pockets for comfort
- :: Suitable as corporate wear, spring & fall wear, and everyday wear
- :: Women's companion style 5317

FABRIC

97% polyester/3% spandex

SIZES

Men's Sizes S-5XL

COLORS

010 Black, 040 Navy, 204 Steel Grey

GARMENT CARE

Machine wash cold with like colors. Tumble dry low.

Do not bleach. Cool iron if needed.

DECORATION RECOMMENDATIONS

Embroidery: Ballpoint 75/10 needle. Two tearaway backings, stacked and roated into a multi-point star. No topical solvent needed.

Heat Transfer: Max heat recommended is 305°F

Screen Printing: Please test for dye migration as it may occur 24 hours later. Automatic printing process is recommended. Maximum number of colors recommended is 2. Ink Recommendations: Poly Low Bleed for white inks and Plastisol for dark inks. Catalyst recommended. Dryer temperature should not exceed 305°F.



AXIS SOFT SHELL JACKET MEN'S 9317	S	М	L	XL	2XL	3XL	4XL	5XL	TOLERANCE
BODY LENGTH measure from neck (CB neck)	28	29	30	30 ¾	31 ½	32 ½	33	33 ½	1/2 +/-
SHOULDER TO SHOULDER	17 1/4	17 ¾	18 1/4	19 1/4	20 1/4	21 1/4	22 1/4	23 1/4	1/2 +/-
CHEST WIDTH 1 inch below armhole	21 ¾	22 ¾	23 ¾	25 ¾	27 ¾	29 ¾	31 3/4	32 ¾	1/2 +/-
BOTTOM OPENING WIDTH RELAXED 1/2	21 1/4	22 1/4	23 1/4	25 1/4	27 1/4	29 1/4	31 1/4	32 1/4	1/2 +/-
SLEEVE LENGTH FROM CB short	33 ½	35	36 1/4	36 ³ ⁄ ₄	37 1/4	37 ¾	39	39 ½	1/2 +/-

KEY TO COMMONLY ABBREVIATED SPEC INFORMATION (ALL MEASUREMENTS ARE IN INCHES)

CB = CENTER BACK

CHEST 1 INCH DOWN = MEASURE THE FRONT OF THE GARMENT 1 INCH DOWN FROM THE ARMHOLE

1/2 = MEASURE ONLY THE FRONT OF THE GARMENT, THEN DOUBLE THAT MEASUREMENT TO GET THE TOTAL CIRCUMFERENCE

RELAXED = DO NOT STRETCH THE GARMENT IF IT HAS ELASTIC TO MEASURE, SIMPLY LEAVE THE ELASTIC RELAXED

STRETCHED = STRETCH THE GARMENT IF IT HAS ELASTIC TO MEASURE, MEASURE STRETCHED

